

Exhibit 50

Sewer/Water Infrastructure Management

Actions



Work Order Data Entry

SR #: 3006898	WO#: 1	Priority: 1	Radio #: 1942	Wtr/Swr: W	WO Stat: CMP	WO Recd Dt:	Orig Prob Cd: CUST
Prob Cd / Primary Ind: 1022N Y		Field Bk Pg/Grid: C11S					
Street# 5748	Frac:	Dir:	Street Name: DESERT VIEW	Sfx: DR	Suite#	Juris: SD	X St:
Inter: DESERT VIEW DR			PALOMINO CR				
Loc Desc: SEE COMMENTS			Thomas Bros Pg: 1248A2				
Job Desc:			Service Area: 2				
Special Inst:			ES Service Area: W				
			Plant Service Area:				
			Assign Dt: 08/31/07 13:20				
			WO Gen Dt: 08/31/07 12:50				

USA#:	Exp Dt:	Fac Typ:	Fac Seq#:	Request: JOY	Ph#: 858 454-8945
-------	---------	----------	-----------	--------------	-------------------

Work Cd	Action Cd	Service Request Comments		ST: 08/31/07 13:40	End: 08/31/07 14:15	JO #:	Emp: 1	Inc: 0.00
ESINV	INV					53546		

WO Comments: Page 1 of 1
 Creation Dt/Tm: 9/4/07 7:50
 Upd Dt/ID: 9/4/07 7:50 LXR

REF VIA PAPER TO 1970 TO LEAK DETECTION ..
 CHECKED HYD TO SEE IF LEAK, SOUND GATE, DIDN'T HEAR ANYTHING - WORK ORDER 2 REFERRED TO RADIO # 1970

Completed by Radio:	Cancel:	Total Crew Hours: 0.28
---------------------	---------	------------------------

Referral:	Priority:	Ref to Radio:	Work Code:	Fac Type:	Fac Seq #:

Last Update Dt: 9/4/07 7:50	Last Update ID: LXR	Last Batch Update Dt: 9/5/07 4:06	Last Batch Update ID: 1975RCLN
WO Completed Dt: 9/4/07 7:50	Completed By: LXR		

Please Wait... Swim is currently sending this screen to your printer.

SR #

3006898

Creation Dt/Tm

09/05/07 15:56

Last Update Dt / ID

09/05/07 15:57 D25

SR Comments

PER 1923, SOUNDED THE SVCS, C/S 10-34, REFER TO STRT DIV FOR RESURFACING OF STREET.....CREATED
SS LOG FOR STRTS.....SD

Page 1 of 1

3006898

08/31/07 16:17

08/31/07 16:17 S50

SR Comments

PER 1942. WILL REFER VIA PPR TO 1970 TO LK DETECT. CS38

Page 1 of 1

3006898

08/31/07 12:50

08/31/07 12:50 D25

SR Comments

PAGED 1942....SD

Page 1 of 1

3006898

08/31/07 12:50

08/31/07 12:50 G4G

SR Comments

STREET IS UNEVEN - SOME BUCKLING UP AND POT HOLES ALL OVER THE STREET, POSSIBLE LEAK
UNDERNEATH THE STREET....YG

Page 1 of 1

Exhibit 51

Hossein Ruhi - Earthquake!

From: Rob Hawk
To: Field Division
Date: September 04, 2007 10:00 AM
Subject: Earthquake!
CC: Boekamp, Patti; Oskoui, Afshin; Zoumaras, Dave

<http://quake.wr.usgs.gov/recenteqs/FaultMaps/117-33.htm>

== PRELIMINARY EARTHQUAKE REPORT ==

California Integrated Seismic Net
 USGS/ Caltech/ CGS/ UCB/ UCSD/ UNR

Version #Q: This report supersedes any earlier reports of this event.
 This event has been reviewed by a seismologist.

A light earthquake occurred at 7:47:59 AM (PDT) on Tuesday, September 4, 2007.
 The magnitude 4.0 event occurred 12 km (8 miles) SW of La Jolla, CA.
 The hypocentral depth is 11 km (7 miles).



Magnitude 4.0 - local magnitude (ML)
 Time Tuesday, September 4, 2007 at 7:47:59 AM (PDT)
 Tuesday, September 4, 2007 at 14:47:59 (UTC)
 Distance from La Jolla, CA - 12 km (8 miles) SW (221 degrees)
 San Diego, CA - 18 km (11 miles) W (266 degrees)
 Balboa Park, San Diego, CA - 19 km (12 miles) WNW (282 degrees)
 Coronado, CA - 19 km (12 miles) WNW (302 degrees)

Coordinates 32 deg. 46.0 min. N (32.767N), 117 deg. 20.4 min. W (117.341W)
 Depth 10.9 km (6.8 miles)
 Location Quality Fair
 Location Quality Parameters Nst=058, Nph=058, Dmin=12 km, Rmss=0.11 sec, Erho=0.3 km, Erzz=0.5 km,
 Gp=216 degrees
 Event ID# ci10276197.
 Additional Information map with fault names
 Google Earth KML (Requires Google Earth.)
 Topo map centered at earthquake (This link takes you offsite.)
 ShakeMap shaking intensity maps
 Waveforms
 SCSN First Motion Mechanism 1
 Did you feel it?
 SCSN Moment Tensor Solution


Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

Tue Sep 4 9:36:21 PDT 2007
106 earthquakes on this map



Magnitude



- LAST HOUR
- LAST DAY
- LAST WEEK



Meters Above Sea Level




Exhibit 52

Sewer/Water Infrastructure Management

Actions



Work Order Data Entry

SR #: 3006898	WO#: 2	Priority: 1	Radio #: 1923	Wtr/Swr: W	WO Stat: CMP	WO Recd Dt:	Orig Prob Cd: CUST
Prob Cd / Primary Ind: 1022N Y		Field Bk Pg/Grd: C11S					
Street# 5748	Frac	Dir	Street Name DESERT VIEW	Sfx DR	Suite#	Jurisd SD	Data Steward: 197D MICHAEL BASOM
Inter: DESERT VIEW DR			PALOMINO CR				
Loc Desc: SEE COMMENTS			Thomas Bros Pg: 1246A2				
Job Desc: UNABLE TO LOCATE LEAK			Service Area: 2				
			ES Service Area: W				
			Plant Service Area:				
			Assign Dt: 09/05/07 07:28				
			WO Gen Dt: 09/04/07 07:50				
Special Inst:							

USAF:	Exp Dt:	Fac Typ:	Fac Seq#:	Request: JOY	Ph#: 858	454-8945
-------	---------	----------	-----------	--------------	----------	----------

Work Cd	Action Cd	Service Request Comments					
LDINV	INV						
LDINV	REF						
		ST: 08/05/07 10:20	End: 08/05/07 11:20	JOY: 53546	Emp: 1	Hrs: 1.00	

WO Comments: Page 1 of 1	SOUND SVC'S, CITY 10-34.. REF TO STREETS TO RESURFACE STREET VIA STA 3B
Creation Dt/Tm: 9/6/07 13:25	
Upd Dt/ID: 9/6/07 13:25 EXP	

Completed by Radio #:	Cancel:	Total Crew Hours: 1.00
-----------------------	---------	------------------------

Referral Priority:	Ref to Radio:	Work Code:	Fac Type:	Fac Seq #:
Job Desc:				

Last Update Dt: 9/6/07 13:25	Last Update ID: EXP	Last Batch Update Dt:	Last Batch Update ID:
WO Completed Dt: 9/6/07 13:25	Completed By: EXP		

Please Wait.... Swim is currently sending this screen to your printer.

SR #

3006898

Creation Dt/Tm

09/05/07 15:56

Last Update Dt / ID

09/05/07 15:57 D25

SR Comments

PER 1923, SOUNDED THE SVCS, C/S 10-34, REFER TO STRT DIV FOR RESURFACING OF STREET.....CREATED
ESS LOG FOR STRTS.....SD

Page 1 of 1

3006898

08/31/07 16:17

08/31/07 16:17 S50

SR Comments

PER 1942. WILL REFER VIA PPR TO 1970 TO LK DETECT. CS38

Page 1 of 1

3006898

08/31/07 12:50

08/31/07 12:50 D25

SR Comments

PAGED 1942....SD

Page 1 of 1

3006898

08/31/07 12:50

08/31/07 12:50 G4G

SR Comments

STREET IS UNEVEN - SOME BUCKLING UP AND POT HOLES ALL OVER THE STREET, POSSIBLE LEAK
UNDERNEATH THE STREET....YG

Page 1 of 1

Exhibit 53

From: <yluza@aol.com>
To: <rhawk@sandiego.gov>
Date: 9/9/2007 1:57:13 AM
Subject: Soledad Mountain Rd. La Jolla

September 9, 2007

Mr. Hawk,

My husband and I spoke to you briefly when you were here a few days ago. You said we could keep you informed on how our street is doing. We, and many of our neighbors, continue to be very concerned because the "patch" in the road appears to be sinking in. And also because at the time of the sewer rupture we had a terrible sewage smell in our bathroom. We had a couple of plumbers check it out but they found nothing wrong with the installation. As soon as the sewer was repaired the smell disappeared but now it is here again and we fear it may another sewer break.

Thank you for your concern.

Yolanda Braunagel

Email and AIM finally together. You've gotta check out free AOL Mail - <http://mail.aol.com>

Exhibit 54

From: Rob Hawk
To: hruhi
Date: Mon, Sep 10, 2007 6:34 AM
Subject: Fwd: Soledad Mountain Rd. La Jolla

Pls see attached. Looks like sewer may be involved too. Who would be the best to contact? Rob

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

From: Rob Hawk
To: JFisher@sandiego.gov; RPalmucci@sandiego.gov
Date: 9/10/2007 8:40:34 AM
Subject: 5735 Soledad Mtn. Rd. concerns/Attorney-Client communication

Additional complaints regarding sewer. Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

CC: AOskoui@sandiego.gov; Greenhalgh, Darren; HRuhi@sandiego.gov;
JBarrett@sandiego.gov

From: <yluza@aol.com>
To: <rhawk@sandiego.gov>
Date: 9/9/2007 1:57:13 AM
Subject: Soledad Mountain Rd. La Jolla

September 9, 2007

Mr. Hawk,

My husband and I spoke to you briefly when you were here a few days ago. You said we could keep you informed on how our street is doing. We, and many of our neighbors, continue to be very concerned because the "patch" in the road appears to be sinking in. And also because at the time of the sewer rupture we had a terrible sewage smell in our bathroom. We had a couple of plumbers check it out but they found nothing wrong with the installation. As soon as the sewer was repaired the smell disappeared but now it is here again and we fear it may be another sewer break.

Thank you for your concern.

Yolanda Braunagel

Email and AIM finally together. You've gotta check out free AOL Mail! -
<http://mail.aol.com>

Exhibit 55

Jim Fisher - Re: Fwd: 5735 Soledad Mtn. Rd. concerns/Attorney-Client communication

From: Christopher Toth
To: Fisher, Jim
Date: 9/10/2007 8:48 AM
Subject: Re: Fwd: 5735 Soledad Mtn. Rd. concerns/Attorney-Client communication

thanks, Jim. We will research this issue today. Chris

>>> Jim Fisher 9/10/2007 8:45 AM >>>
Chris, Not sure if you have seen this. Jim

>>> Rob Hawk 9/10/2007 8:40:26 AM >>>
Additional complaints regarding sewer. Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

Exhibit 56

Jim Barrett - RE: 5735 Soledad Mtn. Rd. concerns/Attorney-Client communication

From: Christopher Toth
To: Hawk, Rob; Oskoui, Afshin
Date: 9/10/2007 1:36 PM
Subject: RE: 5735 Soledad Mtn. Rd. concerns/Attorney-Client communication
CC: Barrett, Jim; Bertch, Tim; Fisher, Jim; Greenhalgh, Darren; Jarrell, David; Ruhi, Hossein

our MWWWD staff investigated this matter this morning (9/10) and determined that the bad sewer odor is coming from the residence's internal plumbing system. The city sewer mains in this area are clear and running free. Please let me know if you have any additional questions or concerns regarding this matter. thanks, Chris

Chris Toth
Deputy MWWWD Director, WWCD
City of San Diego
9150 Topaz Way
San Diego, CA 92123
Phone: 1-858-654-4161
Fax: 1-858-654-4139
cell phone: 1-619-990-4718
email: CToth@SanDiego.gov

>>> Rob Hawk 9/10/2007 12:32 PM >>>
Will do. Rob

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> "Afshin Oskoui" <AOSkoui@SanDiego.gov> 9/10/07 9:07 AM >>>

Rob, can you follow up w/ metro as well. Chris Toth should be breifed on this asap. Since both hossein and I are out, please call Dave Jarrell and breif him as to where we stand. Thx, Afshin

-----Original Message-----

From: "Rob Hawk" RHawk@sandiego.gov
To: JFisher@sandiego.gov
Cc: AOSkoui@sandiego.gov ; DGreenhalgh@sandiego.gov ; HRuhi@sandiego.gov ; JBarrett@sandiego.gov
Sent: 9/10/07 8:40 AM

Subject: 5735 Soledad Mtn. Rd. concerns/Attorney-Client communication

Additional complaints regarding sewer. Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

[Message delivered by NotifyLink]

Exhibit 57

From: Jim Fisher
To: Christopher Toth; Rob Hawk
Date: 9/10/2007 3:12:53 PM
Subject: Re: 5735 Soledad Mtn Rd

Rob, This raises a question about any sewage leakage into the slope and potentially contributing to the slope movement and/or negative impacts on the water system. Jim

>>> Christopher Toth 9/10/2007 2:55 PM >>>

based on earlier email requests today, WWCD staff went to 5735 Soledad Mtn Rd and there only could discover bad sewer odors coming from a bathroom plumbing fixture within the residence. WWCD CCTV footage also exists from the recent past (7/26/2007) wherein WWCD crews televised the sewer main in front of this property. Review of this recent CCTV file shows that the sewer lateral leading from the property is completely filled with roots as it approaches the sewer main.

The property owner needs to be contacted and apprised of this matter. Following our City Council Policy 400-10, the property owner needs to clear the property sewer lateral so that it flows freely. Should a licensed plumber or licensed drain cleaner perform this work, the licensed entity will file a plumber's report if it believes there are any structural problems with the property's sewer lateral on the public street side of the sewer lateral. The property owner is responsible for clearing the sewer lateral completely, regardless of which side of the street a sewer lateral blockage exists.

The large root mass within the sewer lateral is the likely cause of bad sewer odors within the residence, since sewage cannot easily flow from the property to the city sewer main. The city would like to coordinate with a licensed plumber involved in cleaning the sewer lateral so that city forces can trap any large root masses that leave the sewer lateral and potentially could block the downstream public sewer.

Please let me know if you want me or other MWWD employees to contact the property owner regarding this issue. thanks, Chris

Chris Toth
Deputy MWWD Director, WWCD
City of San Diego
9150 Topaz Way
San Diego, CA 92123
Phone: 1-858-654-4161
Fax: 1-858-654-4139
cell phone: 1-619-990-4718
email: CToth@SanDiego.gov

CC: Alex Ruiz; David Jarrell; Jim Barrett; Ray Palmucci; Stan Medina; Tim Bertch

Exhibit 58

Jim Fisher - Fwd: 5735 Soledad Mtn Rd

From: Jim Fisher
To: Stan Medina
Date: 9/10/2007 3:14 PM
Subject: Fwd: 5735 Soledad Mtn Rd

Stan, Look to see where this is relative to the problems we have been having. If there is potential for sewage leakage into the soil we may need to take additional precautionary efforts in the repair of any leaks. Jim

>>> Christopher Toth 9/10/2007 2:55 PM >>>

based on earlier email requests today, WWCD staff went to 5735 Soledad Mtn Rd and there only could discover bad sewer odors coming from a bathroom plumbing fixture within the residence. WWCD CCTV footage also exists from the recent past (7/26/2007) wherein WWCD crews televised the sewer main in front of this property. Review of this recent CCTV file shows that the sewer lateral leading from the property is completely filled with roots as it approaches the sewer main.

The property owner needs to be contacted and apprised of this matter. Following our City Council Policy 400-10, the property owner needs to clear the property sewer lateral so that it flows freely. Should a licensed plumber or licensed drain cleaner perform this work, the licensed entity will file a plumber's report if it believes there are any structural problems with the property's sewer lateral on the public street side of the sewer lateral. The property owner is responsible for clearing the sewer lateral completely, regardless of which side of the street a sewer lateral blockage exists.

The large root mass within the sewer lateral is the likely cause of bad sewer odors within the residence, since sewage cannot easily flow from the property to the city sewer main. The city would like to coordinate with a licensed plumber involved in cleaning the sewer lateral so that city forces can trap any large root masses that leave the sewer lateral and potentially could block the downstream public sewer.

Please let me know if you want me or other MWWD employees to contact the property owner regarding this issue. thanks, Chris

Chris Toth
Deputy MWWD Director, WWCD
City of San Diego
9150 Topaz Way
San Diego, CA 92123
Phone: 1-858-654-4161
Fax: 1-858-654-4139
cell phone: 1-619-990-4718
email: CToth@SanDiego.gov

Exhibit 59

From: Rob Hawk
To: Fisher, Jim
Date: 9/10/2007 4:09:55 PM
Subject: Re: 5735 Soledad Mtn Rd

That is true, but which came first? If it turns out that sewer leaked first, do they get the lead? who makes that call? I hope that all of this is just readjustment and that an equilibrium condition will return to the slope. Rob

>>> Jim Fisher 9/10/07 3:12 PM >>>

Rob, This raises a question about any sewage leakage into the slope and potentially contributing to the slope movement and/or negative impacts on the water system. Jim

>>> Christopher Toth 9/10/2007 2:55 PM >>>

based on earlier email requests today, WWCD staff went to 5735 Soledad Mtn Rd and there only could discover bad sewer odors coming from a bathroom plumbing fixture within the residence. WWCD CCTV footage also exists from the recent past (7/26/2007) wherein WWCD crews televised the sewer main in front of this property. Review of this recent CCTV file shows that the sewer lateral leading from the property is completely filled with roots as it approaches the sewer main.

The property owner needs to be contacted and apprised of this matter. Following our City Council Policy 400-10, the property owner needs to clear the property sewer lateral so that it flows freely. Should a licensed plumber or licensed drain cleaner perform this work, the licensed entity will file a plumber's report if it believes there are any structural problems with the property's sewer lateral on the public street side of the sewer lateral. The property owner is responsible for clearing the sewer lateral completely, regardless of which side of the street a sewer lateral blockage exists.

The large root mass within the sewer lateral is the likely cause of bad sewer odors within the residence, since sewage cannot easily flow from the property to the city sewer main. The city would like to coordinate with a licensed plumber involved in cleaning the sewer lateral so that city forces can trap any large root masses that leave the sewer lateral and potentially could block the downstream public sewer.

Please let me know if you want me or other MWWD employees to contact the property owner regarding this issue. thanks, Chris

Chris Toth
Deputy MWWD Director, WWCD
City of San Diego
9150 Topaz Way
San Diego, CA 92123
Phone: 1-858-654-4161
Fax: 1-858-654-4139
cell phone: 1-619-990-4718
email: CToth@SanDiego.gov

Exhibit 60

Sewer/Water Infrastructure Management

Actions



Work Order Data Entry

SR#: 3010436	Wo#: 1	Priority: 1	Radio #: 1854	Wtr/Swr: W	WO Stat: CMP	WO Recd Dt:	Orig Prob Cd: 1161
Prob Cd / Primary Ind: 1161 Y							Field Bk Pg/Grid: C12S
Street #	Frac	Dir	Street Name	Sfx	Suite#	Juris	Data Steward: 1630 JEFF REMSBURG
5703			SOLEDAD MTN	RD		SD	X St: DESERT VIEW
Inter:							
Loc Desc:			LOTS OF WTR COMING UP OUT OF ST				
Job Desc:			SEE COMMENTS				
Special Inat:							
ISA#:		Exp Dt:	Fac Typ: WTRM	Fac Seq#: 389251	Request: TOM	Plat: 619 997-4359	
Work Cd	Action Cd	Service Request Comments					
RPR	RPR						
		ST: 09/14/07 15:30	End: 09/15/07 02:30	JO #: 53527	Emp: 4	Hrs: 1.00	

NO Comments: Page 1 of 1
 REPAIR LEAKING CORP...INSTALL BAND, REPAIR 3/4" SVC

Creation Dt/Tm: 9/17/07 13:39

Upd Dt/Tm: 9/17/07 13:39 EMP

Completed by Radio: Cancel: Total Crew Hours: 44.00

Referral Priority: Ref to Radio: Work Code: Fac Type: Fac Seq #:

Job Desc:

Last Update Dt: 9/17/07 13:39 Last Update ID: EMP Last Batch Update Dt: Last Batch Update ID:

WO Completed Dt: 9/17/07 13:39 Completed By: EMP

se Wait.... Swim is currently sending this screen to your printer.

Start Sewer/Water L...

SR #

3010436

Creation Dt/Tm

09/14/07 14:06

Last Update Dt / ID

09/14/07 14:06 S50

SR Comments

PGD 1942. CS38

Page 1 of 1

3010436

09/14/07 13:36

09/14/07 13:36

K4C

SR Comments

1942 PGD 1336 9/14/07 KC

Page 1 of 1

3010436

09/14/07 13:31

09/14/07 13:31

L7C

SR Comments

PER CONS AFRAID COULD CAUSE A HILLSLIDE PLS ASAP

Page 1 of 1

Exhibit 61

From: Afshin Oskoui
To: Alex Ruiz; Jim Barrett; Jim Fisher; Ray Palmucci; Rob Hawk
Date: 9/14/2007 1:38:43 PM
Subject: Re: Soledad Mtn Road

Rob, After your visit, if not an urgent situation, please schedule a mtg on Monday and/or Tuesday w/ all involved to see what progress has been made, and what next steps we may need to follow. Thanks,
Afshin

>>> Rob Hawk 09/14/2007 1:32 PM >>>

We have a new leak on the 5700 block according to Mr. Crabbe (5703). I spoke with Johnny Mitchell and he said he would attend to it. I'm headed up there now to see if anything new is going on.
Rob Hawk

>>> Alex Ruiz 8/6/07 10:35 AM >>>

We have crews on site and will provide an update as soon as they can investigate the additional cracking... Our Construction Manager (Johnny Mitchell) is also responding to the scene...

Rob: Can you provide additional inspection of the "new cracks"?

Alex

(619) 533-6692
Assistant Director
Water Department

>>> Thyme Curtis 8/6/2007 9:58 AM >>>

Hello,

Tom Crab just called and said there are new cracks in Soledad Mtn Road, as of today, that seems to indicate a much larger problem and is worried that a major problem needs to be averted.

There are new cracks at 5725 Soledad Mtn. Road, and the ground is sinking. Mr. Crab said that there is a lot of water from the leak, and that crews are working on the leak right now, though the street is cracking very badly "as we speak" and SDG&E has vented the street to prevent an explosion, as there is a gas leak. He was very concerned, I told him I would immediately email his concerns to the proper people.

Thank you,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

>>> Richard Haas 7/19/2007 11:26:42 AM >>>

Hi Thyme,

Jim Barrett, the Director of the Water Department, is researching this problem and is planning to call Mr. Crab back.

Jim or Alex Ruiz (Assistant Director) will send you an e-mail and let you know the summary of their discussions.

Rich

>>> Thyme Curtis 7/19/2007 10:34 AM >>>
Hi Rich,

A constituent named Tom Crab (619.997.4359, 5703 Soledad Mtn Road) just called and is very concerned about Soledad Mtn Road, specifically in front of 5715 Soledad Mtn Road. He said that the street has been sinking and cracking for the past few months, and back in March 2007 he reported a crack in the street that was subsequently patched. Last night a pipe cracked and is currently being fixed by city crews, but Mr. Crab believes something more is going on underneath the street, that it is sinking or moving. He's hoping a geologist or engineer can take a look before something major happens.

Thanks,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

CC: David Jarrell; Hossein Ruhi; Richard Haas

Exhibit 62

From: "Jim Fisher" <JFisher@sandiego.gov>
To: <Hruhi@sandiego.gov>, <RHawk@sandiego.gov>, <JBarrett@sandiego.gov>, <JFisher@sandiego.gov>, <RuizA@sandiego.gov>, <RPalmucci@sandiego.gov>, <SMedina@sandiego.gov>, <JMeda@sandiego.gov>
Date: 9/14/2007 3:11:15 PM
Subject: RE: Soledad Mtn Road

Hossien, I have spoken to Stan Medina and he will make sure it is fixed today. Jim

-----Original Message-----

From: "Hossein Ruhi" Hruhi@sandiego.gov
To: RHawk@sandiego.gov; JBarrett@sandiego.gov; JFisher@sandiego.gov; RuizA@sandiego.gov; RPalmucci@sandiego.gov
Cc: AOskoui@sandiego.gov; RHaas@sandiego.gov
Sent: 9/14/07 2:58 PM
Subject: Re: Soledad Mtn Road

I have left a phone message for John Mitchell that it is urgent to fix this water leak as soon as possible it can not wait until tomorrow as Rob informed me that the crack on the street is growing wider. Jim Fisher is out of the office, any body from water dept. receiving this e-mail PLS help and get a crew there to fix the leak. I have asked Rob to keep an eye on the situation over the weekend. thanks

lh>>> Rob Hawk 09/14/2007 1:32 PM >>>

We have a new leak on the 5700 block according to Mr. Crabbe (5703). I spoke with Johnny Mitchell and he said he would attend to it. I'm headed up there now to see if anything new is going on.
Rob Hawk

>>> Alex Ruiz 8/6/07 10:35 AM >>>

We have crews on site and will provide an update as soon as they can investigate the additional cracking... Our Construction Manager (Johnny Mitchell) is also responding to the scene...

Rob: Can you provide additional inspection of the "new cracks"?

Alex

(619) 533-6692
Assistant Director
Water Department

>>> Thyme Curtis 8/6/2007 9:58 AM >>>

Hello,

Tom Crab just called and said there are new cracks in Soledad Mtn Road, as of today, that seems to indicate a much larger problem and is worried that a major problem needs to be averted.

There are new cracks at 5725 Soledad Mtn. Road, and the ground is sinking. Mr. Crab said that there is a lot of water from the leak, and that crews are working on the leak right now, though the street is cracking very badly "as we speak" and SDG&E has vented the street to prevent an explosion, as there is a gas leak. He was very concerned, I told him I would immediately email his concerns to the proper people.

Thank you,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

>>> Richard Haas 7/19/2007 11:26:42 AM >>>
Hi Thyme,

Jim Barrett, the Director of the Water Department, is researching this problem and is planning to call Mr. Crab back.

Jim or Alex Ruiz (Assistant Director) will send you an e-mail and let you know the summary of their discussions.

Rich

>>> Thyme Curtis 7/19/2007 10:34 AM >>>
Hi Rich,

A constituent named Tom Crab (619.997.4359, 5703 Soledad Mtn Road) just called and is very concerned about Soledad Mtn Road, specifically in front of 5715 Soledad Mtn Road. He said that the street has been sinking and cracking for the past few months, and back in March 2007 he reported a crack in the street that was subsequently patched. Last night a pipe cracked and is currently being fixed by city crews, but Mr. Crab believes something more is going on underneath the street, that it is sinking or moving. He's hoping a geologist or engineer can take a look before something major happens.

Thanks,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

[Message delivered by NotifyLink]

CC: <AOskoui@sandiego.gov>, <RHaas@sandiego.gov>

Exhibit 63

From: Rob Hawk
To: Barrett, Jim; Conf 600B 8 8A; Fisher, Jim; Hawk, Rob; Oskoui, Afshin; Palmucci, Ray; Ruiz, Alex
Date: 9/17/2007
Time: 10:00:00 AM - 10:30:00 AM
Subject: Soledad Mtn Road
Place: Conf 600B 8 8A

Meet to discuss possible action plans to protect public and private improvements.

Recent observations suggest additional distress to improvements. I understand that Water has a crew that will repair the water line tonight, and I will visit the site over the weekend. Except for Dave Jarrell, this was the only opportunity in the near future to capture most of the people involved. I've invited Chris Toth from Sewer also in case he wants to attend, although recent filming of the main did not reveal any damage.

Rob Hawk
cell: 619-980-7161

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> Afshin Oskoui 9/14/07 1:38:27 PM >>>

Rob, After your visit, if not an urgent situation, please schedule a mtg on Monday and/or Tuesday w/ all involved to see what progress has been made, and what next steps we may need to follow. Thanks, Afshin

>>> Rob Hawk 09/14/2007 1:32 PM >>>

We have a new leak on the 5700 block according to Mr. Crabbe (5703). I spoke with Johnny Mitchell and he said he would attend to it. I'm headed up there now to see if anything new is going on.
Rob Hawk

>>> Alex Ruiz 8/6/07 10:35 AM >>>

We have crews on site and will provide an update as soon as they can investigate the additional cracking... Our Construction Manager (Johnny Mitchell) is also responding to the scene...

Rob: Can you provide additional inspection of the "new cracks"?

Alex

(619) 533-6692
Assistant Director
Water Department

>>> Thyme Curtis 8/6/2007 9:58 AM >>>

Hello,

Tom Crab just called and said there are new cracks in Soledad Mtn Road, as of today, that seems to indicate a much larger problem and is worried that a major problem needs to be averted.

There are new cracks at 5725 Soledad Mtn. Road, and the ground is sinking. Mr. Crab said that there is a lot of water from the leak, and that crews are working on the leak right now, though the street is cracking very badly "as we speak" and SDG&E has vented the street to prevent an explosion, as there is a gas leak. He was very concerned, I told him I would immediately email his concerns to the proper people.

Thank you,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

>>> Richard Haas 7/19/2007 11:26:42 AM >>>
Hi Thyme,

Jim Barrett, the Director of the Water Department, is researching this problem and is planning to call Mr. Crab back.

Jim or Alex Ruiz (Assistant Director) will send you an e-mail and let you know the summary of their discussions.

Rich

>>> Thyme Curtis 7/19/2007 10:34 AM >>>
Hi Rich,

A constituent named Tom Crab (619.997.4359, 5703 Soledad Mtn Road) just called and is very concerned about Soledad Mtn Road, specifically in front of 5715 Soledad Mtn Road. He said that the street has been sinking and cracking for the past few months, and back in March 2007 he reported a crack in the street that was subsequently patched. Last night a pipe cracked and is currently being fixed by city crews, but Mr. Crab believes something more is going on underneath the street, that it is sinking or moving. He's hoping a geologist or engineer can take a look before something major happens.

Thanks,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

CC: Haas, Richard; Jarrell, David; Ruhi, Hossein; Toth, Christopher

The purpose of this letter is to inform you that the City of San Diego will be installing above ground piping ("highline") to provide water service to your property beginning on September ??, 2007. At that time, the Water Department will isolate and depressurize (turn-off) the existing underground water main.

The purpose of this action is to minimize any potential damage to the existing water mains due to slope subsidence in the 5700 block of Soledad Mt. Rd. Past subsidence in the area has resulted in damage to the underground water pipelines and we are taking this action in an effort to protect the infrastructure from further damage. Until the areas of subsidence are successfully stabilized, the City will utilize the highline water main to provide reliable water service for your property and other properties that depend upon the subject main.

Exhibit 64

From: Rob Hawk
To: AOskoui@sandiego.gov
Date: Mon, Sep 17, 2007 10:55 PM
Subject: Re: Fwd: Soledad Mt. Rd. Water Line

Afshin & all: take a look at the attached & see if that's what you had in mind. Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> Afshin Oskoui 09/17/07 5:13 PM >>>

Rob, can you add an introductory section to set the stage on what we are going to initiate in the area leading to the water's high lining exercise. I believe Dave was going to talk to Jamaal Batta, and assign him the project management responsibilities. I'll see which PIO we want to use as the contact person, may want to go with Carol Drummond who already have a hotline for our Utilities Undergrounding program. Thanks, Afshin

>>> Jim Fisher 09/17/2007 4:03 PM >>>

Afshin, We have reviewed the water system for the Soledad Mtn Rd area and will be able to remove the main from service. Our plan is to perform two cut & plugs to physically separate the main in the impacted area and highline approximately 10 homes. In addition, we will contact the Fire Department to determine the location and number of hydrants needed for fire protection.

Attached is some language that can be included in the letter to the homeowners. We will be ready to perform this work next week, once the letter has gone out. Please let me know when the letter is sent so that we can schedule the work.

If you have any questions, please let me know. Thanks Jim

CC: DZoumaras@sandiego.gov, HRuhi@sandiego.gov, MGibson@sandiego.gov

Dear Soledad Mountain Road Homeowner:

As you are aware, there have been a series of water leaks on service connections from our main water line on your street, resulting in unanticipated repair to water services, and traffic disruption due to repair activities. The purpose of this letter is to inform you that the City of San Diego will be installing above ground piping ("highline") to provide water service to your property beginning on September ??, 2007. At that time, the Water Department will isolate and depressurize (turn-off) the existing underground water main. In addition, City forces will be conducting a soil investigation in the area to determine the cause of the recent leaks.

The purpose of this effort is to minimize potential for damage to the water main and roadway due to potential soil movement in the 5700 block of Soledad Mountain Road. Past soil movement in the general area in the 1960's and the 1990's resulted in damage to local underground water pipelines. Until the cause of the leaks has been identified and corrected, the City will utilize the highline to provide reliable water service for your property, and other properties that depend upon the subject water main.

We appreciate your patience and cooperation during our activities in the area to protect the utilities, and investigate and identify the cause of the problem. During this time, please contact Carol Drummond at our hotline (_____) if you have any questions. If you notice any service leaks, please immediately call our utility hotline at (619) 515-3525.